

**GOVERNMENT OF TELANGANA
ROADS & BUILDINGS DEPARTMENT**

From,
Sri. B. Mohan, B.E,
District R&B Officer,
Ranga Reddy District,
Goshamahal, Hyderabad-12.

To,
The Principal,
1-13/14, Beside Jaihind Valley,
Near Andhra Bank, Manikonda,
Hyderabad – 500089.

Lr. No. EE(R&B)/RRD/DB/HD/D1/2020-21/310

Dt: 27.07.2020

Gentleman,

Sub:- (R&B) Dept. – Delhi School of Excellence - Structural soundness certificate
- Issue - Regarding.

Ref:- 1) Principal, Delhi School of Excellence, Lr. No. Nil, Dt: 02.07.2020
2) DEE(R&B), Shamshabad Sub-Division, Lr. No. DEE/SHBD/Building/
Soundness/2020-21/ , Dt: 24.07.2020

With reference to your letter 1st cited, it is to inform that the Deputy Executive Engineer (R&B), Shamshabad Sub-Division has reported that as per Manikonda Village Gram Panchayat Office records the building construction permission was accorded on 19.09.2007. The building construction was completed in the year 2011-12.

The Deputy Executive Engineer (R&B), Shamshabad Sub-Division has informed that they have inspected the building superficially and reported that they have observed the following

- 1) The building constructed with Stilt + Ground = 4 Floors.
- 2) Parking Tiles were laid in the parking area in front of building and CC flooring done in the Stilt Parking.
- 3) Vetrified tiled Flooring done in the Ground + 4 Floors.
- 4) Painting was done two years back.
- 5) No Dampness in the External and Internal Walls and Roof Slabs.
- 6) There are small diagonal hair cracks in walls and horizontal cracks at the juncture of roof beam and wall in the three rooms in the 4th Floor. These are needed to be rectified.
- 7) On Terrace Floor, impervious coat layer was damaged at several locations. These are needed to be rectified.
- 8) On Terrace Floor, Column Reinforcement is exposed and getting rusty with weather. Dummy Columns with concrete to be laid.


Cont'd...2

The Deputy Executive Engineer(R&B), Shamshabad sub-Div further reported that Mr. K. Narayana, S.V. Constructions, Rajendranagar, Hyderabad, GHMC certified Licenced Engineer has submitted the structural soundness certificate stating that the building is structurally safe and Soundness and followed the relevant IS Code standards and NBC 2005 during construction.

Therefore, it is to inform that based on the structural soundness certificate given by Mr. K. Narayana, S.V. Constructions, GHMC licensed Engineer, the structural soundness certificate for the structure is issued for one year.

As the structure is inspected superficially, the School management is responsible for the repairs and maintenance of the structure during such period and management is responsible for any structural failures during this period.

Yours faithfully,


District R&B Officer,
Ranga Reddy District.

Copy to Dy. Executive Engineer, Shamshabad Sub Division, Hyderabad for information.